





Front skid plate


Mounting instructions

for Isuzu D-Max 4x4







Hex bolt
M10x1.25x30



Hex bolt
M10x1.25x40




Washer 10x30




Spring washer 10

M12 Bolt Kit


Use M12 Bolt Kit
if your vehicle has
M12 thread



Hex bolt
M12x1.25x35




Washer 12x27




Spring washer 12

Maximum Tightening Torques






M10 (8.8)	50 Nm
-----------	-------






13,14,17,19





17



Screw into original screw



Screw into original screw



Screw into original screwing.
Use M12 Bolt Kit if your vehicle has M12 thread.
Tighten all bolts

